



# MARY ANN

## GUARD - CHASE - SUPPORT

### Main Particulars

Length (OA)	32.70
Breadth	7.00 m
Depth	3.60 m
Gross Tonnage	177
Net Tonnage	53
Deck Area	50 m2

### Registry

Vesse Type	GUARD - CHASE - SUPPORT
Year of Construction	1972
Refurbished	2016
Ship Builder	Visser & Zoon N.V.
Class	RINA
Flag	Vanuatu
Port of Registry	Port Vila
Official Number	2316
IMO Number	7211842
MMSI Number	577256000
Call Sign	YJTV2

### Machinery

Main Engine	Stork Werkspoor
Power	877 BHP
Generators	2 x DAF 75/60kW

### Capacities

Fuel Oil	60 m3
Potable Water	11 m3
Water Maker	1000 tr. / 24h
Freezer Storage	3 m3
Dry Storage	30 m3

### Performance

Cruise Speed	9 kn
Exposure	42 days

### Navigation Equipment

Radar	Furuno FR2117 Furuno FR8062
GPS Navigation	2 x Furuno GP-32
Auto Pilot	Simrad AP45
Electronic Charts	MaxSea

### Communication

GMDSS Area	A1 - A2 - A3
MF / HF Radio	Furuno FS-1562-25
VHF Radio	Furuno FM8500 Furuno FM8800

Portable VHF	Icom IC-GM1600E
Navtex	Furuno NX500
Inmarsat C	Furuno Fe com 18

### Life Saving Equipment

Life Saving Appliances	6 persons
Regulations	IACS Rec. No. 99
Lifebuoys	6 pcs
Lifejackets	9 pcs
Liferafts	2 x 6 persons
EPIRB	Jotron Tron 30S MKII
SART	Jotron Tronsart

### Fire Safety Equipment

Regulations	IACS Rec. No. 99
-------------	------------------

### Accommodation

Cabins	6 x 1 persons
Airconditioning	Yes

### Contact

E-mail address	maryann@v.m.vu
----------------	----------------



Strandweg 7

1976 BS IJmuiden-Holland

+31 (0) 255 - 518449

+31 (0) 6 54 68 32 10

info@vanlaar.maritime.com

www.vanlaar.maritime.com